

FITTER / WELDER

Davis Iron and Davis Steel Metal Fabrication

Job Description

- Certified MIG / FCAW Welder, capable of welding 3G, and 4G
- Years experience? Minimum 1 year (counting class-time in welding field)
- Must be able to read structural steel drawings and fit-up according to the drawing
- Operate a torch for cutting metal
- Operate Overhead cranes
- Ability to read a tape measure down to the 16th and ability to read a Micro-meter
- Non-Smokers only
- You must be willing to work in other areas as needed and requested.
- Non air-conditioned building
- Quitting time is not set in stone for employees working in the Warehouse. It is normally 3:00, but if there is a truck to unload, or load, they will be required to stay and take care of that before leaving. It could be 6:00, or at times it could even be 10:00. That isn't often, but it does happen.
 - 1ST Shift: 6:00 a.m. until work is done. Can go until later in the evening.
 - 2nd Shift: 5:00 p.m. until work is done. Can go until early morning hours.
- After our interview, if we are interested, we would require the following:
 - Drug Test
 - Physical